



# 危险品 **Dangerous Goods**

# 货物运输条件鉴别报告书

Identification and Classification Report For Sea Transport of Goods

报告编号 Report No.: S03A24070730H00701

电动自行车 N1 Air ST(内置锂离子电池 CZM240702 36V 10Ah

物品名称: 360Wh)

Name of Goods: Electric bicycle N1 Air ST(Containing Rechargeable Li-ion

Battery CZM240702 36V 10Ah 360Wh)

委托单位: 东莞镁迪电子有限公司

Dongguan Maidi Electronics Co., Ltd Applicant:

签发日期:

2024-11-15 Issue Date:



发行机构:广测集团

Web: www.gtggroup.com E-mail: info@gtggroup.com Tel.: 86-400 755 8988

### 货物运输条件鉴别报告书

#### Identification and Classification Report For Sea Transport of Goods

luentiii	cation and Classification Report For Sea Transport of Goods		
委托单位 Applicant	东莞镁迪电子有限公司 Dongguan Maidi Electronics Co., Ltd		
委托单位地址 Applicant Address	广东省东莞市塘厦镇平山工业大路 105 号 101 室 Room 101, No. 105, Pingshan Industrial Road, Tangxia Town, Dongguan, Guangdong		
生产单位 Manufacturer	东莞创智美科技有限公司 Dongguan CZM Technology Co., LTD		
生产单位地址 Manufacturer Address	广东省东莞市大岭山镇石大路大岭山段 79 号 2 栋 501 Room 501, Building 2, No. 79, Dalingshan Section, Shida Road, Dalingshan Town		
物品信息 Nature of the goods	该物品是锂离子电池 CZM240702,装在设备中。 This goods is Rechargeable Li-ion Battery CZM240702, in the equipment. 规格参数/Specifications: 36V 10Ah 360Wh 电池尺寸/Battery Size: 451mm*54mm*58mm 每包装件中电池/电芯数量/Number of batteries/cells per package: 1PCS 每个包装件中电池(电芯)的净重/Battery(Cell) net quantity of per package: 2.043kg 每一包装件毛重/Gross weight of each package: 25kg 该电池的 UN38.3 检验报告由广东储能检测技术有限公司提供。报告书编号为: S03A24070730U00701。 The battery UN38.3 inspection report by Guangdong ESTL Technology Co., Ltd. Report No.: S03A24070730U00701.		
鉴别日期 Identification Date	2024-11-15		
报告有效期 The period of validity	2024年11月15日至2024年12月31日		
鉴别依据 Identification Criteria	IMDG CODE(Amdt 41-22)		
鉴别结论 Conclusion	危险物品 Dangerous Goods UN 编号(UN No.): UN3171 危险货物类别(Class or Div): 9		
备注 Comment	注:电池或电芯必须加以保护,防止短路,设备必须采取措施防止意外启动。 Note: Batteries or cells must be protected against short circuit, and measures must be taken to prevent accident that the protected against short circuit, and measures must be taken to prevent accident that the protected against short circuit, and measures must be taken to prevent accident that the protected against short circuit, and measures must be taken to prevent accident that the protected against short circuit, and measures must be taken to prevent accident that the protected against short circuit, and measures must be taken to prevent accident that the protected against short circuit, and measures must be taken to prevent accident that the protected against short circuit.		
检测 Tested by / / / / / / / / / / / / / / / / / /	甲核 Reviewed by 多新語 Approved by 投告专用章 Special Seal for Report		





### 货物运输条件鉴别报告书

# Identification and Classification Report For Sea Transport of Goods

项目编号				
Item No.	S03A24070730H00701			
物品名称	中文名称	电动自行车 N1 Air ST(内置锂离子电池 CZM240702 36V		
Name of Goods	Name of Chinese 10Ah 360Wh)		·	
	英文名称	Electric bicycle N1 Air ST(Containing Rechargeable Li-ion		
	Name of English	Battery CZM24070	2 36V 10Ah 360Wh)	
鉴别项目名称			检查结果	
Item			Inspection Result	
该电池额定瓦特小时数为 360Wh。			>100Wh	
Watt-hour rating of the battery is 360Wh.				
锂电池已通过 UN38.3 测试。			符合	
Each battery is of a type proved to meet the Requirements of each			Conform	
test in the UN MANUAL	OF TESTS AND CRITE			
section 38.3.				
电池按照规定的质量管理体系进行制造。			符合	
Batteries be manufactured under a quality management			Conform	
programme.				
该锂电池不属于召回电池,不属于废弃和回收电池。			符合	
The Lithium batteries do not belong to batteries returned to the			Conform	
manufacturer for safety	reasons, are not waste			
and not lithium batteries	being shipped for recyc			
通过包装件 1.2 米跌落试验。			不适用	
Each package is capabl	e of withstanding a 1.2r	Not applicable		
orientation.				
包装件需要按照特殊规定 188 的要求进行适当标记。			不适用	
The package must be a	ppropriately marked acc	Not applicable		
provision 188.				
每票货物均有随附文件说明:			不适用	
包装件内装锂离子电池或电芯;			Not applicable	
必须小心操作。如包装件破损,有易燃危险性;				
包装件破损时应采取的特殊措施,包括必要时的重新包装;				
应急电话号码。				
Each consignment is ac	companied with a docu			
indication that:				
the package contains lit	hium ion cells or batteri			
the package must be ha				
hazard exists if the pack	•			
special procedures shou	uld be followed in the ev			
damaged, to include inspection and repacking if necessary and a				
telephone number for a	dditional information.			

# Photos of Samples and Labels/样品照片及标识

### 包装件 Package:





### 电池 Battery:



--- 报告结束 ---

--- End of Report ---

## 声明

## **Declaration**

1. 本报告无批准人、审核人及鉴定人签名无效。

The test report is invalid without the signatures of Ratifier, Reviewer and Testing engineer.

2. 对检验报告若有异议,应于收到报告之日起十五天内向检验单位提出。

Objections to the test report must be submitted to ESTL within 15 days.

3. 未经本试验室书面同意,不得部分地复制本报告。

Nobody is allowed to photocopy or partly photocopy this test report without written permission of ESTL.

4. 本报告仅对送检样品负责。

The test report is valid for the tested samples only.

5. 本报告涂改无效。

The test report is invalid if altered.